

# Product Update Bulletin #6441

FieldLink


March 29, 2013

**Affected Products:** *All FieldBlock FNT, FNP, FNS models, and 6-point Drop Connectors (DR465036A, DR465037A, DR465038A, DR465039A, DR465040A, DR465041A, DR465042A, DR465043A, DR465044A, DR465045A, DR465046A, DR465047A)*

## Design Change Notification


In preparation for hazardous location approvals for the FieldLink FN and 6-Drop din rail mount drop connectors, we have changed from pluggable terminals blocks to fixed terminal blocks. The blocks look the same but have been fastened in place.

This was done so that these products meet the standards for Class 1, Division 2 and ATEX/IECEX hazardous location approvals.



If your applications are not hazardous locations and you prefer pluggable terminal blocks, please contact StoneL Customer Service, we can easily customize these to your specifications.

Best Regards,



Bob Jensen  
Director of Technical Solutions  
StoneL  
Phone: (218) 737-0732  
e-mail: [bjenson@stonel.com](mailto:bjenson@stonel.com)